


## Product Change Notification

FIBRAIN Sp. z o.o. would like to inform about the design modification of fiber optic cables from the EAC group. Please note that the change relates to the position of the grooves in the cable sheath. The grooves have been offset from the reinforcement strength members by 90 degrees. According to the above, the line marked by the grooves indicates directly the place where the center of the window cutting tool should be placed in the cable. The described method of making the incision prevents from damaging strength members placed in the cable sheath.

The cables with the modification are marked with an additional marking: "CUT ON THE GROOVE AREA".

These changes do not affect parameters or mechanical properties of the cable.



*Łoziska Anna*

Technical Manager of passive  
components department

[www.fibrain.com](http://www.fibrain.com)

FIBRAIN Sp. z o.o.  
36-062 Zaczeranie 190F  
Poland

phone +48 17 866 08 00  
fax +48 17 866 08 10  
e-mail info@fibrain.com